

VESSEL SUMMARY REPORT
INTERNAL

Name of vessel LANTAU ACE	DNV GL Id no. G94618	IMO no. 9216353
-------------------------------------	--------------------------------	---------------------------

Vessel information

DNV GL id. no.	G94618	Operational status	In Operation
IMO no.	9216353		
Vessel name	LANTAU ACE	Signal letters	V7CW5
Type		Port of registration	Majuro
Date of keel laid	2000-11	Flag	Marshall Islands
Date of build	2001-04-18		
Date of commissioning	Not available	Equipment letter	Not available
Gross tonnage (ITC 69)	14278	Gross tonnage (pre 69)	Not available
Previous name(s)	AGLAIA(2009)LANTAU ACE(2009)LANTAU ACE(2017)ST.JOHN MIRACLE(2011)		
Main class	100 A5	Dual class	
Class notation	Container ship SOLAS-II-2,Reg.19 IW		

Owner / Manager / DOC Holder information

Owner	Reederei MS Bitburg GmbH & Co. KG	Owner no.	10351275
Manager	Köpping Reederei GmbH & Co. KG	Manager no.	10036316
Address	Heideweg 2		
City/ZIP	24813 Schülp b. RendsburgSchleswig-Holstein		
	Schülp b. Rendsburg		
Country	Germany		
DOC Holder	Köpping Reederei GmbH & Co. KG	DOC Holder no.	10036316

Vessel Certificates

Class Certificates

Certificate description	Code	Issued	Station	Valid until	Ext. until	Type	Status
Classification Certificate	CLCE	2019-04-30		2021-04-30		FullTerm	

Statutory Certificates

Certificate description	Code	Issued	Station	Valid until	Ext. until	Type	Status
Load Line Certificate	ILLC	2018-07-07	Manchester	2021-04-30		FullTerm	
Cargo Ship Safety Construction Certificate	CCC	2018-07-07	Manchester	2021-04-30		FullTerm	
Cargo Ship Safety Equipment Certificate	CEC	2018-07-07	Manchester	2021-04-30		FullTerm	
Cargo Ship Safety Radio Certificate	CRC	2018-07-07	Manchester	2021-04-30		FullTerm	
Safety Management Certificate	SMC	2019-02-19	Istanbul	2024-03-04		FullTerm	

VESSEL SUMMARY REPORT
INTERNAL

Name of vessel LANTAU ACE	DNV GL Id no. G94618	IMO no. 9216353
-------------------------------------	--------------------------------	---------------------------

Certificate description	Code	Issued	Station	Valid until	Ext. until	Type	Status
International Ship Security Certificate	ISPS-IC	2019-02-27	Lisbon	2024-03-04		FullTerm	
Maritime Labour Certificate	MLC-IC	2018-08-01	Lisbon	2023-08-18		FullTerm	
International Oil Pollution Prevention Certificate, Type A	OPP-A-IC	2018-07-07	Manchester	2022-08-23		FullTerm	
International Sewage Pollution Prevention Certificate	SPP-IC	2018-07-07	Manchester	2021-04-30		FullTerm	
Air Pollution Prevention Certificate	IAPP	2019-04-03	Hamburg Environmental Certification	2021-04-30		FullTerm	
Energy Efficiency Certificate	EEC	2018-07-07	Manchester			FullTerm	
International Anti-Fouling System Certificate	AFS-IC	2018-07-07	Manchester			FullTerm	
Ballast Water Management Certificate - Exchange Method	BWMC-E	2018-07-07	Manchester	2021-04-30		FullTerm	
Document of Compliance for the Carriage of Dangerous Goods	IDG-IC	2018-07-07	Manchester	2021-04-30		FullTerm	
Declaration of Compliance with ILO Convention No.92	ILO92	2018-07-07	Manchester			FullTerm	
Declaration of Compliance with ILO Convention No.133	ILO133	2018-07-07	Manchester			FullTerm	
Tonnage Certificate (1969)	TMC	2018-07-07	Manchester			FullTerm	

Vessel Surveys

Class surveys

Survey description	Code	Fee	Last survey	Station	Next survey	TW	Postponed	Status
Main class renewal	MC.R	3195	2016-03-02	Singapore	2021-04-30	3/0		
Main class intermediate	MC.In	1623	2019-07-20	Manchester	2023-10-31	9/9		
Main class annual	MC.A	1542	2019-07-20	Manchester	2020-04-30	3/3		
Hull items	HS.Sa	0	2019-07-20	Manchester		0/0		
Machinery items	MS.Sa	12373	2016-03-02	Singapore		0/0		
Bottom complete survey	BOT.C	355	2019-02-24	Valencia	2021-04-30	0/0		
Propeller shaft arrangement C oil	CPRPSO	101	2016-03-02	Singapore	2020-08-22	9/6		

VESSEL SUMMARY REPORT

INTERNAL

DNV·GL

Report date:
2019-08-22

Name of vessel
LANTAU ACE

DNV GL Id no.
G94618

IMO no.
9216353

Survey description	Code	Fee	Last survey	Station	Next survey	TW	Postponed	Status
lubricated								
Shaft - propeller connection, conical keyless C	CPRPCN	51	2011-02-22	Singapore	2026-02-22	9/6		
Auxiliary boiler, composite 1	AUSBOI	870	2019-02-17	Haifa	2021-04-30	0/0		
Dangerous goods class notation DG complete	DG.C	2508	2016-03-02	Singapore	2021-04-30	9/0		
Periodically unattended machinery space complete	E0.C	1065	2016-03-02	Singapore	2021-04-30	9/0		
Periodically unattended machinery space annual	E0.A	355	2019-07-20	Manchester	2020-04-30	3/3		

Statutory surveys

Survey description	Code	Fee	Last survey	Location	Next survey	TW	Postponed	Status
Load line renewal	ILLC.R	406	2016-03-02	Singapore	2021-04-30	3/0		
Load line annual	ILLC.A	791	2019-07-14	Barcelona FIS	2020-04-30	3/3		
Safety construction renewal	CCC.R	761	2016-03-02	Singapore	2021-04-30	3/0		
Safety construction intermediate	CCC.In	0	2019-07-20	Manchester	2023-10-31	9/9		
Safety construction annual	CCC.A	0	2019-07-20	Manchester	2020-04-30	3/3		
Safety equipment renewal	CEC.R	1014	2016-03-02	Singapore	2021-04-30	3/0		
Safety equipment periodical	CEC.In	811	2019-07-20	Manchester	2023-10-31	9/9		
Safety equipment annual	CEC.A	1105	2019-07-20	Manchester	2020-04-30	3/3		
Safety radio renewal	CRC.R	0	2016-03-02	Singapore	2021-04-30	3/0		
Safety radio periodical	CRC.A	193	2019-07-14	Barcelona FIS	2020-04-30	3/3		
Document of compliance for the carriage of dangerous goods renewal	IDG.R	2508	2016-03-02	Singapore	2021-04-30	3/0		
Safety management - vessel, renewal audit	ISM-VE.R	1700	2019-02-19	Istanbul	2024-03-04	3/0		
Safety management - vessel, intermediate audit	ISM-VE.In	1700	2017-02-28	Istanbul	2021-09-04	6/6		
Ship security renewal audit	ISPS.R	1700	2019-02-27	Lisbon	2024-03-04	3/0		
Ship security intermediate audit	ISPS.In	1700	2017-02-28	Istanbul	2021-09-04	6/6		

VESSEL SUMMARY REPORT
INTERNALName of vessel
LANTAU ACEDNV GL Id no.
G94618IMO no.
9216353

Survey description	Code	Fee	Last survey	Location	Next survey	TW	Postponed	Status
Maritime Labour Convention renewal	MLC.R	1700	2018-08-01	Lisbon	2023-08-18	3/0		
Maritime Labour Convention intermediate	MLC.In	1700	2016-08-05	Piraeus	2021-02-18	6/6		
Oil pollution prevention, type A renewal	OPP-A.R	558	2017-08-23	Lisbon	2022-08-23	3/0		
Oil pollution prevention, type A intermediate	OPP-A.In	304	2014-07-12	Port Kelang, Malaysia	2020-02-23	9/9		
Oil pollution prevention, type A annual	OPP-A.A	619	2019-07-20	Manchester	2020-08-23	3/3		
Sewage pollution prevention renewal survey	SPP.R	862	2016-03-02	Singapore	2021-04-30	3/0		
Air pollution prevention renewal	IAPP.R	659	2016-03-02	Singapore	2021-04-30	3/0		
Air pollution prevention intermediate	IAPP.In	0	2019-07-20	Manchester	2023-10-31	9/9		
Air pollution prevention annual	IAPP.A	619	2019-07-20	Manchester	2020-04-30	3/3		
Ballast water management certificate renewal	BWMC.R	870	2017-07-29	Manchester	2021-04-30	3/0		
Ballast water management certificate intermediate	BWMC.In	508	2019-07-14	Barcelona FIS	2023-10-31	9/9		
Ballast water management certificate annual	BWMC.A	580	2019-07-14	Barcelona FIS	2020-04-30	3/3		

Conditions

Conditions related to class

	No.	Issued date	Issued at	Due Date	Postponed	Status
CC	39	2019-07-14	Barcelona FIS	2019-07-31	2021-04-30	Due
Main class intermediate (MC.In) survey, deficiencies: The deficiencies noted during MC.In have been assessed and found acceptable until given due date. Prior to completion of the MC.In, the deficiencies must be brought in order for the following areas/items: - Damaged web frame 54 in ballast wing tank 5S						
Findings: [Ballast double side tank 5S(051-057)] Frame 54 (3rd web frame from aft) found indented in between first and second side longitudinals, counting from above.						

VESSEL SUMMARY REPORT

INTERNAL

DNV·GL

Report date:
2019-08-22

Name of vessel
LANTAU ACE

DNV GL Id no.
G94618

IMO no.
9216353

Conditions related to statutory certificates

	No.	Issued date	Issued at	Due Date	Postponed	Status
RR	9	2017-12-19	Environmental Protection	2022-08-23		
Ballast water management - treatment: The vessel shall meet the D-2 standard according to Reg. B-3 (ref. IMO Res. MEPC.297(72) adopted on 2018-04-13): A) at the latest until its first Oil Pollution Prevention (OPP) renewal survey following the 2017-09-08, if 1. this survey is completed on or after 2019-09-08 or if 2. a renewal survey was completed on or after 2014-09-08 but prior to 2017-09-08, or, B) until its second OPP renewal survey following the 2017-09-08, if the first renewal survey following the 2017-09-08 is completed prior to the 2019-09-08, provided that the conditions of Reg. B-3.10.1.2 are not met. Precondition is having an approved BWM system installation (retrofit project) inclusive approved BWM plan (or Appendix to the BWM plan) and Operation Manual for D-2 standard. This RR shall be deleted by the approval engineer, when the documents required for a D-2 standard retrofit have been approved.						
RR	10	2017-12-19	Class & Statutory Certificates, HAM / Certificates & Records Management	2022-08-23		
Ballast water management - treatment: The vessel must be initially surveyed for D-2 compliance and must hold an 'International Ballast Water Management Certificate' documenting compliance with the performance standard - treatment - (D-2 standard): A) at the latest until its first Oil Pollution Prevention (OPP) renewal survey following the 2017-09-08, if 1. this survey is completed on or after 2019-09-08 or if 2. a renewal survey is completed on or after 2014-09-08 but prior to 2017-09-08, or, B) until its second OPP renewal survey following the 2017-09-08, if the first renewal survey following the 2017-09-08 is completed prior to the 2019-09-08, provided that the conditions of Reg. B-3.10.1.2 are not met (ref. IMO Res. MEPC.297(72) adopted on 2018-04-13). This RR shall be deleted by the surveyor, when a BWM certificate for D-2 standard is issued.						
NC	30	2019-02-19	Istanbul	2019-05-19		CAP Accepted
ISM Code 1.2.3 The safety management system should ensure: .1 compliance with mandatory rules and regulations: Each ship that has rechargeable systems containing ozone-depleting substances shall maintain an ozone depleting substances record book, either in the form of a separate record book, or as part of an existing onboard logbook. Operations including recharge, repair/maintenance, discharge to atmosphere (deliberate/non-deliberate), discharge to reception facilities and supply shall be entered in the logbook.						

Memoranda

Memoranda to Owner

	No.	Issued date	Issued at
MO	13 Ref 260	2017-08-23	Lisbon
Surveys for non harmonized OPP international certificates: The Oil pollution prevention (OPP) survey has been advanced and the OPP certificate de-coupled from the Harmonized System of Survey and Certification (HSSC) as accepted by The Republic of the Marshall Islands. Before change of flag the new Administration to be consulted for their acceptance to continue the de-harmonized OPP survey scheme. This memo shall be deleted by the surveyor who is performing the renewal survey for re-coupling			

VESSEL SUMMARY REPORT

INTERNAL

DNV·GL

Report date:
2019-08-22

Name of vessel
LANTAU ACE

DNV GL Id no.
G94618

IMO no.
9216353

No.	Issued date	Issued at
(harmonization).		

Memoranda to Surveyor

No.	Issued date	Issued at
MS	832 Ref 207f	2017-10-25 Class & Statutory Certificates, Høvik
Re-issuance of electronic certificates - preparation comments: This MS shall be deleted/partially deleted after issuance of full term electronic certificates. MLC: Please check and update Date of Registry and/or DMLC issue date in the certificate. IDG: If DG 101 has not been previously prepared or issued (yellow status without QA), DG47.73a should be used. If none of the forms have been previously issued in LIFT a QA is triggered and the surveyor should wait for the completion of this before proceeding with issuing DG 101 and accepting the certificate. Only one form should be used and the other shall be discarded.		
MS	833 Ref 281	2018-05-02 Periodical Service Agreements
This vessel is marked for Flexible invoicing: Invoices will be handled centrally in Oracle only. Invoices will no longer be handled in SAP. Cost collection will be handled locally in Oracle or Team. Invoices shall be sent from DNV GL AS Norway as the contract partner.		
MS	835 Ref 43	2018-12-19 PSA department Høvik
Temporary Ref 43 only to ensure that the logic for picking up the correct Service Code for Service Contract coverage is in place. This temporary Ref 43 going to be removed once this is resolved and none should issue a regular Ref 43 for a vessel with Ref 281. Regarding flexible invoicing see Ref 281.		
MS	821 Ref 149	2015-11-20
Ship Security Plan approval: The Ship Security Plan (SSP) has been approved according to ISPS Code (SOLAS XI-2) requirements at the place and on the date shown below. 1) DNV GL unit (survey station) having approved the SSP: GL (approver: ANKSCH) 2) Date of SSP approval: 2014-08-05 3) Ship's flag: Marshall Islands 4) DOC-holders DNV GL identification: 10036316 [Köpping Reederei GmbH & Co. KG] 5) Company identification number (IMO): 5442534		
MS	825 Ref 201a	2016-03-02 Singapore
Lifeboat / rescue boat on-load release mechanism not applicable: The vessel is not provided with life boat on-load release mechanism. The vessel is freefall lifeboat. Rescueboat is equipped with off-load release mechanism.		
MS	834 Ref 184a	2018-08-01 Lisbon
Declaration of Maritime Labour Compliance (DMLC) Part II review for vessel: DMLC Part II has been reviewed and found to comply with Maritime Labour Convention (MLC), 2006 and DMLC Part I. 1) DNV GL unit (survey station) having reviewed the DMLC Part II: GL (reviewer: J. Ribbat) 2) Date of DMLC Part II review: 2013-07-30 3) Ships's flag: Marshall Islands		

VESSEL SUMMARY REPORT INTERNAL

DNV·GL

Report date:
2019-08-22

Name of vessel
LANTAU ACE

DNV GL Id no.
G94618

IMO no.
9216353

No.	Issued date	Issued at
4) DOC-holders DNV GL identification: 10036316 [Köpping Reederei GmbH & Co. KG] 5) Company identification number (IMO): 5442534 6) Date of review of MLC, 2006 amendments item 15, 16: 2018-08-01 7) DNV GL unit (survey station: Lisbon, Portugal; Inspector Name :Antonio Roleira Marinho)		
MS	837 Ref 232b	2019-05-13 Hamburg - Statutory / Technical Support
IACS PR17 -> Deficiencies possibly affecting the implementation of the ISM Code: Follow up required at next scheduled ship audit. Report issued by: DNV GL station HAIFA at ASHDOD/ISRAEL on 2019-04-16 Focus areas: SEE PR17 REPORT Possible Safety Management System (SMS) failures identified by surveyor as above. Details of the report are available in NPS, in correspondence for vessel J.no. 10409. This MS shall be deleted by the auditor after next audit and results shall be reflected in the audit report.		